## **Trouble Shooting the V2 (2 Button)**



Possible Cause Power point is faulty	Possible Solution  Repair power point. Test power point with another appliance
	I topan porter point reet porter point with another appliance
Unit in Winter mode	V2 - Hold up or down button for 3 seconds to return to summer mode. V2-1 & V2 Deluxe - Press Select button till Auto light on
Controller has failed	Return to manufacturer for repair
Fault with pump	Plug pump direct into power point and test
Controller in Start Delay mode roof or limit light flashing	Wait for controller to start or press any button to over-ride
Pump not plugged into controller	Plug pump into base of controller marked PUMP
Wrong software selected - V2	Turn power off 3 sec. switch back on, if a 33 appears in start up routine, alter software. Turn power off for 3 sec. press and hold up and down buttons while turning power on. Switch power off and on again to check that the 33 has gone - repeat if not.
Wrong software selected - V2-1 of V2 Deluxe Low Filter Pump pressure (Boosted systems only)	Turn power off, remove lid and check that Flow Switch Jumper Pin J1 is selected to off.
	Clear filter pump lint pot and Skimmer basket - remove suction cleaner
Poof concer coble discourse to d	Defit roof concer coble to far right hand plus assist
	Refit roof sensor cable to far right hand plug socket
	Check cable for damage and repair/replace
power surge	Swap Roof & Pool sensors - If fault doesn't change to 77 return unit for repair. If 77 is displayed check/replace roof sensor.
Roof temp reading out of normal range	Replace Roof sensor
Roof sensor cable Short Circuit	Check cable for damage and repair/replace
Roof Cable polarity wrong	Reverse cable connections at Roof sensor plug
Short circuit in Roof sensor	Replace Roof sensor
Pool sensor cable disconnected	Refit pool sensor cable to the left of roof sensor plug - no gap between them
Damaged Pool sensor cable	Check cable for damage and repair/replace
Unit damaged by lightning or power surge	Swap Pool & Roof sensors - If fault doesn't change to 99 return unit for repair. If 99 is displayed check/replace pool sensor.
	<del></del>
Pool sensor reading out of normal range	Check Pool sensor wires are not reversed
Pump not primed	Prime pump and plug into direct power point and run till pipe is cooled
Pool sensor cable Short Circuit	Check cable for damage and repair/replace
	Reverse cable connections at Pool sensor plug
	Replace Pool sensor
Chart of our first oor oor foot	1.05.000 1.001
ID	Prime pump and plug into direct power point and run till pipe is
	Fault with pump Controller in Start Delay mode roof or limit light flashing Pump not plugged into controller Wrong software selected - V2 Wrong software selected - V2-1 of V2 Deluxe Low Filter Pump pressure (Boosted systems only)  Roof sensor cable disconnected Damaged Roof sensor cable Unit damaged by lightning or power surge  Roof temp reading out of normal range  Roof sensor cable Short Circuit Roof Cable polarity wrong Short circuit in Roof sensor  Pool sensor cable disconnected  Damaged Pool sensor cable Unit damaged by lightning or power surge  Pool sensor reading out of normal range  Pool sensor reading out of normal range